### Retractable In-Desk Box Solution with USB-C, HDMI & USB 3.0, and Intuitive Touch Control Excellence





**Quickstart Guide** 



WyreStorm recommends reading through this document in its entirety to become familiar with the product's features prior to starting the installation process.



### 

- Read through the Wiring and Connections section for important wiring guidelines before creating or choosing premade cables.
- Visit the product pages to download the latest firmware, document version, additional documentation, and configuration tools.

#### **Before You Start**

The following tools may be required for installation:











Electric Drill

Hole Saw Bit

Band Tape

Marker Pen

Phillips Screwdriver

### **Package Contents**

WARNING: This product contains small items that could be a choking hazard if swallowed. Before installation, verify that all parts are included and undamaged.




Note: The serial to 4-I/O cable, and the hook and loop strip set are not included in the package of IDB-300 unit.


### Installation

- 1. Drill an 80mm/3.15" diameter hole into the table.


Recommended table depth: within 45mm/1.77"

- Unscrew the KB2.5\*5 screw to detach the cable bushing and the cable pass-through plate from the cable access enclosure.
- 3. Insert the cable access enclosure into the hole.







4. Install the mounting bracket under the table using the three Φ3.0\*10mm screws included.



5. Thread the thread sleeve onto the cable access enclosure clockwise from below the table.




Insert one end of the cables through the cable holder's slots and the counterbalance parts respectively as the following shown




**Note:** The length of each cable from the end without locking connector to the cable holder shall not exceed 1.2m.


7. Affix the cable holder to the mounting bracket using the M2.5\*5mm() and M3\*5mm() screws included.




8. Pass the cables upward through the cable access enclosure's corresponding holes, and insert the cable pass-through plate and the cable bushing through the cables in sequence. Then apply the KB2.5\*5 screw into the cable access enclosure.




9. Pass the two I/O female connectors of the enclosure through the mounting bracket's slots, and connect them to the two of the I/O male connectors accordingly, then attach the serial to I/O cable under the table using the self-adhesive hook and loop strip set.




**Note:** You may need to use a cable tie to bundle the four I/O male connectors together to affix them securely under the table. This step is not applicable to the IDB-300 unit.



10. Place each cable in an individual compartment of the cable bag included. Affix the cable bag to the four sides of the mounting bracket through the already installed hook and loop strip of the bracket and the bag.





# **Specifications**

Technical	
Control	2x Touch Buttons (IDB-300-BTN Only)
HDMI Cable	HDMI 2.0   Length: 2m
USB-C Cable	USB 3.1 Gen1   Length: 2m
USB-A to USB-B Cable	USB 3.0   Length: 1.8m
Serial to I/O Cable	Length: 1m
Environmental	
Operating Temperature	0 to + 45°C (32 to + 113 °F), 10% to 90%, non-condensing
Storage Temperature	-20 to +70°C (-4 to + 158 °F), 10% to 90%, non-condensing
Mounting	Flush tabletop mount
<b>Mounting Dimensions and Weight</b>	
Enclosure Dimenstions (W x H)	88mm x 75mm/3.46" x 2.95"
Recommended Table Opening	80mm/3.15"
Min/Max Table Thickness	5mm - 45mm/0.2" - 1.77"
Weight	0.15Kg/0.33lbs (for enclosure only)
Regulatory	
Safety and Emission	CE   FCC   RoHS   RCM   EAC   UKCA

# **Warranty Information**

WyreStorm Technologies ProAV Corporation warrants that its products to be free from defects in material and workmanship under normal use for a period of five (5) years from the date of purchase. Refer to the Product Warranty page on wyrestorm.com for more details on our limited product warranty.

